


Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-229	Smoke	8/11/2009	ADS/TM	S21MM_008MH	Dry	Yes	753.88



Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-229	Smoke	8/11/2009	ADS/TM	S21MM_008MH	Dry	Yes	753.88

Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S21MM_026G2	S21MM_026MH	S21MM_016MH	66.7567	8
S21MM_004G1	S21MM_004MH	S21MM_012MH	86.4654	8
S21MM_026G1	S21MM_026MH	S21MM_037MH	87.6883	8
S21MM_011G1	S21MM_011MH	S21MM_004MH	185.783	8
S21MM_016G1	S21MM_016MH	S21MM_008MH	20.2453	8
S21MM_008G1	S21MM_008MH	S21MM_004MH	306.942	8

Observations & Photos

Obs_ID S1028-229-OB01
Address 2207 Lynnbrook Ave
Status Private
Source Cleanout

Location Yard - back

Nearest MH S21MM_037MH

Comments Smoke from cleanout in back yard. 2207 Lynnbrook Ave.



Picture \S1028-229-OB01-P01.jpg


Comments Back of house, 2207 Lynnbrook Ave.

Obs_ID S1028-229-OB02
Address 2844 Woodbrook Ave
Status Private
Source Cleanout

Location Yard - back

Nearest MH S21MM_016MH

Comments Smoke from cleanout in back yard. 2844 Woodbrook Ave.



Picture \S1028-229-OB02-P01.jpg

Comments Back of house, 2844 Woodbrook Ave.

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-229	Smoke	8/11/2009	ADS/TM	S21MM_008MH	Dry	Yes	753.88

Obs_ID S1028-229-OB03

Address 2818 Woodbrook Ave

Status Private

Source Cleanout

Location Yard - back

Nearest MH S21MM_004MH

Comments Smoke from cleanout in back yard in paved concrete. 2818 Woodbrook Ave.



Picture \S1028-229-OB03-P01.jpg

Comments Back of house, 2818 Woodbrook Ave.